
## Wickiup Dam & Reservoir—Construction Period 1939-1949

## Location: On the Deschutes River 9 miles west of LaPine, Oregon



Top: Camp facilities. Center: Camp kitchen. Bottom: Camp shops and storage garage.



1939 - Wickiup Reservoir Clearing by Civilian Conservation Corp (CCC) enrollees.






1939 - Wickiup Dam Outlet Works Top: Excavation and clearing begins. Bottom: Conduit excavation partially complete.



1939 - Wickiup Dam Embankment Civilian Conservation Corps (CCC) Top Left: Enrollees compacting fill on downstream face. Top Right: Type of soil excavated. Cut-off trench. Center: Stripping dam site. Bottom Left: Compacting cut-off trench. Bottom Right: Dragline excavating cut-off trench.



1940 - Wickiup Dam. View towards right abutment.



1940 - Wickiup Dam. View along dike from left abutment.



1940 - Wickiup Dam outlet works. Early stages of concrete construction.




1940 - Wickiup Dam outlet works. Concrete finishing. Valve house structure.



1940 - Wickiup Dam outlet works. Foundation grouting.



1940 - Wickiup Dam outlet works. Ring follower gate shafts.



1940 - Wickiup Dam intake and outlet works. Completed contract construction.